

VIAFIX: Repair to a Failed Utility Reinstatement

Demonstration in live traffic and foul weather conditions



Catastrophic failure of trench reinstatement located in the wheel track (Nov 2009)



Dangerous pothole filled with standing water and debris – Viatec applied direct into water and broken asphalt



A permanent repair in freezing, wet conditions, without cutting or TM is possible with Viatec – Repair took 30 sec



Viatec can take traffic loads immediately – No matter how appalling the conditions are



After Viatec was laid in foul weather, freezing conditions and trafficked immediately, it still stands in the road 22 months later (Aug 2012)