

Repair to a failed utility reinstatement Viafix demo in live traffic and foul weather conditions



Catastrophic failure of trench reinstatement located in the wheel track (Nov 2009)



Dangerous pothole filled with standing water and debris –
Viafix applied direct into water and broken asphalt



A permanent repair in freezing, wet conditions, without cutting or TM is possible with **Viafix** – Repair took 30 seconds



Viafix can take traffic loads immediately – No matter how appalling the conditions are



After **Viafix** was laid in foul weather, freezing conditions and trafficked immediately, it still stands in the road months later (Sep 2010)